

Toshiba America Energy Systems' experience with F-Class generators reflects the uniqueness of this specific class of equipment. While workscopes for these machines include repairs for known technical issues, it is equally important to provide in-depth inspections and assessments in order to uncover other systemic problems. This careful analysis, conducted by our experienced staff of generator engineers, helps ensure worry-free operation once the equipment is put back into service.

At our Milwaukee Service Center, we offer:

- Complete or partial rotor rewinds
- J-Strap and main lead replacement/reconditioning
- Spacer block repairs
- Amortissuer assembly repairs
- Collector ring machining and replacement
- High-speed balancing

On-site stator services include:

- Complete stator rewinds
- Stator rewedges, with modified ripple spring designs
- Addressing loose end winding hardware and blocking issues
- Stator electrical testing
- Clean, inspect and test hydrogen seal assemblies





Toshiba America Energy Systems 6623 West Washington Street, West Allis, WI 53214 Phone: 414.475.2800 | www.toshiba.com/taes